

Tool Kits

The early kits included with the T500 models , up to the 1973 K models (to be confirmed) included a box wrench having a universal joint and a removable handle. which were items 2 and 3 in the left photo below. These were definitely no longer included by the 1975 M series tool kits. The contact points file (part 09813-00001) appears to have been included up until the R series in 1971, and as an option in 1972 - beyond that the parts manuals I have do not list them . The points wrench (09930-20111) appears to have been included up to the J models (to be confirmed) and then as an option beginning with the K in 1973.

Early kit supplied with K models - included item 2 and 3 for total of 16 pieces.

◆ Tool Kit

A tool kit which includes all tools needed for daily maintenance is provided inside the battery & tool cover.



Fig. 32 Tool kit

1. Tool bag
2. Universal box wrench
3. Box wrench handle
4. Box wrench handle bar
5. 32 mm offset wrench
6. 22 mm offset wrench
7. Offset wrench handle
8. 14 x 17 mm open end wrench
9. 10 x 12 mm open end wrench
10. 8 mm open end wrench
11. 21 mm box wrench
12. 14 mm box wrench
13. Cross head screw driver
14. Combination screw driver
15. Screw driver handle
16. Pliers


Kit supplied with the M model Titan and GT's - 14 pieces.

TOOL KIT

A tool kit which includes all tools needed for daily maintenance is provided inside the left frame cover.

1. Tool bag
2. 14 x 17 mm open end wrench
3. 10 x 12 mm open end wrench
4. 8 mm open end wrench
5. 32 mm offset wrench
6. 22 mm offset wrench
7. Offset wrench handle
8. Combination screw driver
9. Cross head screw driver
10. Box wrench handle bar
11. Screw driver handle

12. 21 mm box wrench
13. 14 mm box wrench
14. Pliers



60

Below are photos of the tools from an early tool kit.

On the right I have included a photo of two of the universal box wrenches (part number 09816-00018) as they differ. One has a longer shank, and as well the shoulder where the shank meets the universal fitting is smaller. There are no visible manufacturer's marks on the ones I have - presumably different suppliers were used, or it may be that one is an earlier one than the other.

